ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8802240193 DOC.DATE: 88/02/19 NOTARIZED: NO DOCKET #
FACIL:50-335 St. Lucie Plant, Unit 1, Florida Power & Light Co. 05000335
50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co. 05000389
AUTH.NAME AUTHOR AFFILIATION
WOODY,C.O. Florida Power & Light Co.
RECIP.NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Responds to violations noted in Insp Repts 50-335/87-25 & 50-389/87-24.Corrective actions:procedure revised.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2
TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL
	PD2-2 PD	1	1	TOURIGNY,E	2	2
INTERNAL:	ACRS	2	2	AEOD	1	1
	DEDRO	1	1	NRR MORISSEAU,D	1	1
	NRR/DLPQ/PEB11B	1	1	NRR/DLPQ/QAB10A	1	1
	NRR/DOEA DIR11E	1	1	NRR/DREP/EPB10D	1	1
	NRR/DREP/RPB10A	2	2	NRR/DRIS DIR9A2	1	1
	NRR/PMAS/ILRB12	1	1	OE LIEBERMAN,J	1	1
	OGC 15-B-18	1	1	REG FILE	1	1
	RES/DRPS DIR	1	1	RGN2 FILE 01	1	1
EXTERNAL:	LPDR	1	1	NRC PDR	1	1
	NSIC	1	1			

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24

R I D S / A D D S

R I D S / A D D S

P. O. BOX 14000, JUNO BEACH, FL 33408-0420

FPL

FEBRUARY 19 1988

L-88-81
10 CFR 2.201

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: St. Lucie Units 1 and 2
Docket Nos. 50-335 and 50-389
Inspection Report 335/87-25 and 389/87-24

Florida Power & Light Company has reviewed the subject inspection report, and pursuant to the provision of 10 CFR 2.201, the response is attached.

Very truly yours,

C. O. Woody
Executive Vice President

COW/EJW/gp

Attachment

cc: Dr. J. Nelson Grace, Regional Administrator,
Region II, USNRC
Senior Resident Inspector, USNRC, St. Lucie Plant

GRM/016.IR

8802240193 880219
PDR ADOCK 05000335
Q DCD

IE01
1/1

ATTACHMENT

FINDING:

During the Nuclear Regulatory Commission (NRC) inspection conducted on November 1 - December 5, 1987, a violation of NRC requirements was identified. The violation involved entering an operational mode without the necessary limiting conditions for operation (LCO) being met. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1987), the violation is listed below:

> Unit 1 Technical Specification (TS) 3.0.4 requires that entry into an operational mode shall not be made unless the limiting conditions for operation (LCO) are met without reliance on provisions contained in the action statement, unless otherwise expected.
>
> Contrary to the above, on October 14, 1987, Unit 1 entered Mode 4 from Mode 5 without the conditions of LCO 3.6.6.2 being met. Shield building integrity was not being maintained due to a door that was left open and unattended.

RESPONSE

1. Florida Power & Light Company concurs with the violation.

2. Procedural deficiency and personnel error in paperwork review by the operators involved were the cause of the finding.

3. Shield Building integrity was immediately established. The shift was conuseled on the need for an accurate and thorough review of shift paperwork prior to mode changes. Additionally, shift meetings were held by the Operations Supervisor on November 30, 1987, December 7, 1987, and January 19, 1988, to discuss the details of this report. The need for thoroughness and accuracy in review of paperwork and operator responsibilities was also emphasized.

4. OP1-0030120, Pre-start Check-Off, will be revised, adding a sign-off signifying that vital areas are revitalized prior to entry into Mode 4. This will ensure that the Shield Building door and all similar areas are locked or controlled prior to required mode changes.

5. Implementation of these measures will be completed by March 31, 1988.

GRM/016.IR