# CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9905190177 DOC.DATE: 99/05/12 NOTARIZED: NO DOCKET #
FACIL:50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244
AUTH.NAME AUTHOR AFFILIATION
MECREDY,R.C. Rochester Gas & Electric Corp.
RECIP.NAME RECIPIENT AFFILIATION
VISSING,G.S.

SUBJECT: Forwards LER 99-004-00 IAW 10CFR50.73 & 10CFR21.Further assessment will be provided in suppl to LER by 990630.

DISTRIBUTION CODE: IE28T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 145
TITLE: Licensee Event Report (LER) & Part 21 Rept Combination (50 Dkt)

NOTES:License Exp date in accordance with 10CFR2,2.109(9/19/72). 05000244

| | RECIPIENT ID CODE/NAME | COPIES LTTR | COPIES ENCL | RECIPIENT ID CODE/NAME | COPIES LTTR | COPIES ENCL |
|---|---|---|---|---|---|---|
| | LPD1-1 LA | 1 | 1 | LPD1-1 PD | 1 | 1 |
| | VISSING,G. | 1 | 1 | | | |
| INTERNAL: | ACNW | 1 | 1 | AEOD/SPD/RRAB | 1 | 1 |
| | DEDRO | 1 | 1 | FILE CENTER | 1 | 1 |
| | NRR/DE/EEIB | 1 | 1 | NRR/DE/EMCB | 1 | 1 |
| | NRR/DE/EMEB | 1 | 1 | NRR/DIPM/IOLB | 1 | 1 |
| | NRR/DIPM/IQMB | 1 | 1 | NRR/DLPM | 1 | 1 |
| | NRR/DRIP/REXB | 1 | 1 | NRR/DSSA/SPLB | 1 | 1 |
| | NRR/DSSA/SPSB | 1 | 1 | RES/DET/EIB | 1 | 1 |
| | RGN 1 | 1 | 1 | RGN 2 | 1 | 1 |
| | RGN 3 | 1 | 1 | RGN 4 | 1 | 1 |
| | RGN1 FILE 01 | 1 | 1 | | | |
| EXTERNAL: | INPO RECORD CTR | 1 | 1 | L ST LOBBY WARD | 1 | 1 |
| | LITCO STUART,VA | 1 | 1 | NOAC MAYS,G | 1 | 1 |
| | NOAC QUEENER,D | 1 | 1 | NRC PDR | 1 | 1 |
| | NUDOCS FULL TXT | 1 | 1 | | | |

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 29 ENCL 29

CATEGORY 1 DOCUMENT

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001 AREA CODE 716 546-2700

ROBERT C. MECREDY
Vice President
Nuclear Operations

May 12, 1999

U.S. Nuclear Regulatory Commission
Document Control Desk
Attn: Guy S. Vissing
Project Directorate I-1
Washington, D.C. 20555

Subject: LER 1999-004, Containment Recirculation Fan Moisture Separator Vanes Incorrectly Installed Results in Unanalyzed Condition
R.E. Ginna Nuclear Power Plant
Docket No. 50-244

Dear Mr. Vissing:

The attached Licensee Event Report LER 1999-004 is submitted in accordance with 10 CFR 50.73, Licensee Event Report System, item (a) (2) (ii) (A), which requires a report of, "Any event or condition that resulted in the condition of the nuclear power plant, including its principal safety barriers, being seriously degraded; or that resulted in the nuclear power plant being: (A) In an unanalyzed condition that significantly compromised plant safety", and in accordance with 10 CFR 21, "Reporting of Defects and Noncompliances". A further assessment will be provided in a supplement to this LER which will be submitted by June 30, 1999.

Very truly yours,

Robert C. Mecredy

xc: Mr. Guy S. Vissing (Mail Stop 8C2)
Project Directorate I-1
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

U.S. NRC Ginna Senior Resident Inspector

1/1
IE28

9905190177 990512
PDR ADOCK 05000244
S PDR