NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: [| | | | |] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | F L S L S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 3 5 (7) | 0 5 1 1 8 0 (8) | 0 6 1 0 8 0 (9)
DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During power ascension, CEA 19 dropped to full insertion. Action in
03 accordance with T.S.3.1.3.1e was initiated with reactor power at 18%.
04 The power supply unit for CEA 19 had failed. The power supply was
05 replaced and CEA 19 was aligned with its CEA group height. On 5-11-80
06 CEA 58 dropped. Appropriate action was taken and CEA 58 was restored to
07 its group position. Similar occurrences were reported as LERs
08 335-76-37, 78-21, 79-6, 80-2.

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
09	R B (11)	E (12)	A (13)	I N S T R U (14)	P (15)	Z (16)

(17) LER/RO REPORT NUMBER

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
8 0	–	0 2 3	/	0 3	L	–	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
A (18)	Z (19)	B (20)	Z (21)	0 0 0 0	N (23)	N (24)	N (25)	P 3 1 4 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of both dropped CEAs was due to failed 15V power supply units
11 (SU-UNI-30A-BV). Both CEAs were restored in 30 minutes or less and
12 normal operation was resumed. Since these power supplies are of a new
13 type, it is possible that the recent failures are associated with the
14 initial break-in period.

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
15	B (28)	0 1 8 (29)	NA	A (31)	Operator Observation

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
16	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
17	0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
18	0 0 0 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
19	Z (42)	NA

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
20	N (44)	NA	

NAME OF PREPARER M. A. Schoppman. PHONE: 305-552-3802

8006230495