REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8012100538 DOC.DATE: 80/09/12 NOTARIZED: NO DOCKET #
FACIL:50-335 St. Lucie Plant, Unit 1, Florida Power & Light Co. 05000335
AUTH.NAME AUTHOR AFFILIATION
PACE,P.L. Florida Power & Light Co.
RECIP.NAME RECIPIENT AFFILIATION
Region 2, Atlanta, Office of the Director

SUBJECT: LER 80-038/03L:on 800813,during normal operation,CEDM 7 failed,dropping dual control element assembly to full insertion.Caused by failed timing module.Module was replaced CEDM 7 was operationally tested & returned to svc.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+1
TITLE: Incident Reports

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL
ACTION:	CLARK,R. 04	3	3			
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08	1	1	A/D OP REACT09	1	1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12	1	1	A/D TECHNOLOG13	1	1
	ACC EVAL BR 14	1	1	AEOD	2	2
	ASLBP/J.HARD	1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 16	1	1	CONT SYS BR 17	1	1
	CORE PERF BR 18	1	1	D/DIR,HUM FAC19	1	1
	DIR,ENGINEERI20	1	1	DIR,HUM FACT S21	1	1
	DIR,SYS INTEG22	1	1	EFF TR SYS BR23	1	1
	EQUIP QUAL BR25	1	1	GEOSCIENCES 26	1	1
	I&C SYS BR 29	1	1	I&E 05	2	2
	JORDAN,E./IE	1	1	LIC GUID BR 30	1	1
	LIC QUAL BR 31	1	1	MATL ENG BR 32	1	1
	MECH ENG BR 33	1	1	MPA	3	3
	NRC PDR 02	1	1	OP EX EVAL BR34	3	3
	OR ASSESS BR 35	1	1	POWER SYS BR 36	1	1
	RAD ASSESS BR39	1	1	REACT SYS BR 40	1	1
	REG FILE 01	1	1	REL & RISK A 41	1	1
	~~SFTY PROG~~ EVA42	1	1	STRUCT ENG BR44	1	1
	SYS INTERACT B45	1	1			
EXTERNAL:	ACRS 46	16	16	LPDR 03	1	1
	NSIC 05	1	1	TERA:DOUG MAY	1	1

DEC 11 1980

AD 4

TOTAL NUMBER OF COPIES REQUIRED: LTTR 69 ENCL 69

JF