NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | F L S L S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 1 (4) | | | (5)
LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T
0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 3 5 (7) | 0 2 2 1 8 1 (8) | 0 3 2 3 8 1 (9)
DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During power operation, 1 of 2 chlorine detectors in the north control
0 3 room air intake failed and was repaired several times during a period
0 4 from Feb. 21 thru Feb. 28. Action was taken per T. S. 3.3.3.6a for each
0 5 occurrence. The detector was out of service briefly on Feb. 21 and 22, about
0 6 13 hours on Feb. 24, 8 hours on Feb. 25 and from 1500 on Feb. 26 thru 2300
0 7 on Feb. 28. Health and safety of public not affected. This is second
0 8 LER of this type. See LER 335-76-36.

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
0 9	S G (11)	E (12)	B (13)	I N S T R U (14)	E (15)	8 (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 1	—	0 1 2	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
B (18)	B (19)	B (20)	B (21)	0 0 0 0 0	N (23)	N (24)	A (25)	W 0 2 5 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The apparent cause of the failure was a loose connection on the reset
1 1 button. Operation of the detector and electronics were checked and found
1 2 to be satisfactory. The button was replaced.
1 3
1 4

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	E (28)	1 0 0 (29)	NA	A (31)	OPERATOR OBSERVATION

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	NA

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
2 0	N (44)	NA	

NAME OF PREPARER KEN SIMMONS PHONE: (305) 552-3815

8104140563