CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9901060295 DOC.DATE: 98/12/31 NOTARIZED: NO DOCKET #
FACIL:STN-50-530 Palo Verde Nuclear Station, Unit 3, Arizona Publi 05000530
AUTH.NAME AUTHOR AFFILIATION
OVERBECK,G.R. Arizona Public Service Co. (formerly Arizona Nuclear Power
RECIP.NAME RECIPIENT AFFILIATION
Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 98-002-01,prepared & submitted pursuant to 10CFR50.73.LER describes discovery & correction of cross-wired power supply receptacle for "B" train hydrogen recombiner.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 145
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:Standardized plant. 05000530

	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL
	PD4-2 PD	1	1	FIELDS,M	1	1
INTERNAL:	ACRS	1	1	AEOD/SPD/RAB	2	2
	AEOD/SPD/RRAB	1	1	FILE CENTER	1	1
	NRR/DE/ECGB	1	1	NRR/DE/EELB	1	1
	NRR/DE/EMEB	1	1	NRR/DRCH/HICB	1	1
	NRR/DRCH/HOHB	1	1	NRR/DRCH/HQMB	1	1
	NRR/DRPM/PECB	1	1	NRR/DSSA/SPLB	1	1
	RES/DET/EIB	1	1	RGN4 FILE 01	1	1
EXTERNAL:	L ST LOBBY WARD	1	1	LITCO BRYCE,J H	1	1
	NOAC POORE,W.	1	1	NOAC QUEENER,DS	1	1
	NRC PDR	1	1	NUDOCS FULL TXT	1	1

C A T E G O R Y 1 D O C U M E N T

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23

A04

APS
Commitment. Innovation. Energy.

Palo Verde Nuclear
Generating Station

Gregg R. Overbeck
Vice President
Nuclear Production

TEL 602/393-5148
FAX 602/393-6077

Mail Station 7602
P.O. Box 52034
Phoenix, AZ 85072-2034

192-01037-GRO/DGM/RAS
December 31, 1998

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, D.C. 20555-0001

Dear Sirs;

Subject: **Palo Verde Nuclear Generating Station (PVNGS)**
Unit 3
Docket No. STN 50-530
License No. NPF-74
Licensee Event Report 98-002-01

Attached please find the supplement to Licensee Event Report (LER) 50-530/98-002 prepared and submitted pursuant to 10 CFR 50.73. This LER describes the discovery and correction of a cross-wired power supply receptacle for the "B" train Hydrogen Recombiner. The power supply receptacle was configured such that had it been utilized, the blower motor of the supplied Hydrogen Recombiner would have rotated in the reverse direction.

Copies of this LER are being forwarded to the appropriate Regional Office and Resident Inspector in accordance with 10CFR50.73(d) and 10CFR50.4(b)(1). APS makes no new regulatory commitments in this LER supplement. If you have questions regarding this submittal, please contact Daniel G. Marks, Section Leader, Regulatory Affairs, at (602) 393-6492.

Sincerely,

Gregg R. Overbeck

IE22

GRO/DGM/RAS/rlh
Attachment

cc: E. W. Merschoff (all with attachment)
J. H. Moorman
M. B. Fields
INPO Records Center

9901060295 981231
PDR ADOCK 05000530
S PDR