U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: |__|__|__|__|__|__| (1)

0 1 | 7 8 9 | M I D C C 1 (2) LICENSEE CODE 14 | 15 0 0 0 0 0 0 0 0 0 0 0 (3) LICENSE NUMBER 25 | 26 4 1 1 1 1 1 (4) LICENSE TYPE 30 | 57 (5) CAT 58

CON'T
0 1 | 7 8 | REPORT SOURCE L (6) 60 61 0 5 0 0 0 3 1 5 (7) DOCKET NUMBER 68 | 69 1 2 2 9 7 8 (8) EVENT DATE 74 | 75 0 1 1 6 7 9 (9) REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | ON 12-29-78 THE INDICATION FOR PRESSURIZER LEVEL CHANNEL TWO WAS DISCOVERED TO HAVE

0 3 | A DEVIATION OF APPROXIMATELY FIVE PER CENT FROM THE OTHER TWO CHANNELS. THE

0 4 | CHANNEL TWO BISTABLES WERE PLACED INTO THE TRIP MODE PURSUANT TO T.S. TABLE 3.3-3

0 5 | ITEM 1D ACTION STATEMENT 14B. SIMILAR OCCURRENCES INCLUDE RO 050-315/78-10,41

0 6 | 59 AND 050-316/78-61.

0 7 |

0 8 | 7 8 9   80

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
0 9	I A (11) 9 10	X (12) 11	Z (13) 12	I N S T R U (14) 13 18	T (15) 19	Z (16) 20

	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.
(17) LER/RO REPORT NUMBER	7 8 21 22	__ 23	0 6 5 24 26	/ 27	0 3 28 29	L 30	__ 31	0 32

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
X (18) 33	X (19) 34	Z (20) 35	Z (21) 36	0 0 0 0 37 40	N (23) 41	N (24) 42	N (25) 43	B 0 8 0 (26) 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | THE CAUSE OF THE PROBLEM WAS ATTRIBUTED TO A GAS POCKET LOCATED IN THE SENSING

1 1 | LINE. THE SENSING LINE WAS REFILLED TO REMOVE THE GASES AND UPON RESTORATION,

1 2 | CHANNEL INDICATION RETURNED TO NORMAL. A DESIGN CHANGE (RFC-12-1598) HAS BEEN

1 3 | ISSUED TO RECTIFY THIS PROBLEM.

1 4 | 7 8 9   80

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	D (28) 9	0 0 0 (29) 10 12	NA 13 44	B (31) 45 46	CHANNEL CHECK 80

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z (33) 9	Z (34) 10 11	NA 44	NA 45 80

	PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37) 9 11	Z (38) 12	NA 13 80

	PERSONNEL INJURIES NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40) 9 11	NA 12 80

7801220132

	LOSS OF OR DAMAGE TO FACILITY TYPE	DESCRIPTION (43)
1 9	Z (42) 9 10	NA 80

	PUBLICITY ISSUED	DESCRIPTION (45)	NRC USE ONLY
2 0	N (44) 9	NA 10	|__|__|__|__|__|__|__|__|__|__|__| 68 69 80

NAME OF PREPARER T. P. Beilman   PHONE: 616-465-5901

GPO 917-926