REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8301170331 DOC.DATE: 83/01/10 NOTARIZED: NO DOCKET #
FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
AUTH.NAME AUTHOR AFFILIATION
HUNTER,R.S. Indiana & Michigan Electric Co.
RECIP.NAME RECIPIENT AFFILIATION
DENTON,H.R. Office of Nuclear Reactor Regulation, Director

SUBJECT: List of outages of boron injection,accumulatons & refueling water storage tank for Jan 1976 - Dec 1980,per NUREG-0737, Item II.K.3.17 & 820826 informal submittal.

DISTRIBUTION CODE: A046S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2
TITLE: OR Submittal: TMI Action Plan Rgmt NUREG-0737 & NUREG-0660

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL
	NRR ORB1 BC 01	7	7			
INTERNAL:	ELD/HDS3	1	0	IE/DEP DIR 33	1	1
	IE/DEP EPDS	1	1	IE/DEP/EPLB	3	3
	NRR PAWLSON,W.	1	1	NRR/DHFS/DEPY29	1	1
	NRR/DL DIR 14	1	1	NRR/DL/ADL 16	1	1
	NRR/DL/ADOR 15	1	1	NRR/DL/ADSA 17	1	1
	NRR/DL/ORAB 18	3	3	NRR/DSI/ADRP 26	1	1
	NRR/DSI/ADRS 27	1	1	NRR/DSI/AEB	1	1
	NRR/DSI/ASB	1	1	~~NRR/DSI/RAB~~	1	1
	NRR/DST DIR 30	1	1	REG FILE 04	1	1
	RGN3	1	1			
EXTERNAL:	ACRS 34	10	10	FEMA-REP DIV	1	1
	INPO,J.STARNES	1	1	LPDR 03	2	2
	NRC PDR 02	1	1	NSIC 05	1	1
	NTIS	1	1			

TOTAL NUMBER OF COPIES REQUIRED: LTTR 47 ENCL 46

INDIANA & MICHIGAN ELECTRIC COMPANY

P. O. BOX 18
BOWLING GREEN STATION
NEW YORK, N. Y. 10004

January 10, 1983
AEP:NRC:0398I

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2
Docket Nos. 50-315 and 50-316
License Nos. DPR-58 and DPR-74
NUREG-0737, ITEM II.K.3.17

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulatory
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Denton:

This letter and its attachment documents our informal submittal of August 26, 1982 to your Consultant regarding NUREG-0737, Item II.K.3.17. The attachment lists the outages of the Boron Injection Tank, Accumulators and Refueling Water Storage Tank for the period of January 1, 1976 through December 31, 1980 for both Unit Nos. 1 and 2. This letter completes the submittal of information for the Cook Plant required for the subject Item.

This document has been prepared following Corporate Procedures which incorporate a reasonable set of controls to ensure its accuracy and completeness prior to signature by the undersigned.

Very truly yours,

R. S. Hunter
Vice President

cc: John E. Dolan - Columbus
M. P. Alexich
R. W. Jurgensen
W. G. Smith, Jr. - Bridgman
R. C. Callen
G. Charnoff
NRC Resident Inspector at Cook Plant - Bridgman

A046

Attachment

Listed below are the outages for the Boron Injection Tank, Accumulators and Refueling Water Storage Tank for the period of January 1, 1976 through December 31, 1980. There were no outages found for the RWST.

DATE	DURATION	EQUIPMENT	REASON
May 17, 1976	3 hr. 45 min.	Unit 1 Boron Injection Tank	Low Boron Concentration
September 8, 1977	5 hr. 15 min.	Unit 1 Boron Injection Tank	Low Boron Concentration
June 12, 1978	1 hr. 4 min.	Unit 2 Boron Injection Tank	Low Boron Concentration
July 14, 1978	7 hr. 28 min.	Unit 1 BIT Outlet Piping Heat Trace	Low Temperature
June 2, 1978	77 Days*	Safety Injection Flowpath Throttle Valves	Incorrectly Set
September 23, 1978	1 hr. 45 min.	Unit 1 Accumulator #1	Boron Concentration Low
October 23, 1978	0 hr. 45 min.	Unit 2 Boron Injection Tank	Boron Concentration Low
July 2, 1979	1 hr. 44 min.	Unit 2 Boron Injection Tank	Boron Concentration Low
August 4, 1980	1 hr. 33 min.	Unit 1 Boron Injection Tank	Boron Concentration Low
July 28, 1980	0 hr. 10 min.	Unit 2 Accumulator	Pressure High

*Subsequent analysis by AEPSC showed that the flow available was sufficient for the Safety Analysis (LER 315/78-050; Condition Report Number 1-8-78-450).