NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | MIDCC2 (2) | 0000000000 (3) | 41111 (4) | (5)
LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T 01 | REPORT SOURCE L (6) | 05003116 (7) | 020880 (8) | 030480 (9)
DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 DURING NORMAL OPERATION, STEAM GENERATOR NUMBER 3 LEVEL INDICATION BECAME ERRATIC
03 AND WAS DECLARED INOPERABLE, THUS, NOT MEETING THE INSTRUMENT OPERABILITY REQUIRE-
04 MENTS OF T.S. TABLES: 3.3-1 ITEM 14 AND 3.3-3 ITEM 5.a AND 6.2. THE APPROPRIATE
05 BISTABLES WERE PLACED IN THE TRIP POSITION AND NUMBER 3 STEAM GENERATOR LEVEL WAS
06 PLACED IN MANUAL CONTROL. PREVIOUS OCCURRENCES INCLUDE: RO-050-315/79-52 AND 53.
07
08

09 SYSTEM CODE IA (11) | CAUSE CODE E (12) | CAUSE SUBCODE E (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE T (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 80 | — | SEQUENTIAL REPORT NO. 009 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN C (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER B080 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 INVESTIGATION REVEALED THAT THE TRANSMITTER, MANUFACTURED BY BARTON-MODEL NO. 764,
11 WAS CAUSING THE ERRATIC INDICATION. ANOTHER TRANSMITTER WAS INSTALLED, CALIBRATED
12 AND THE AFFECTED STEAM GENERATOR LEVEL CHANNEL WAS RETURNED TO SERVICE. THE
13 REPLACED TRANSMITTER WAS SENT TO ITT BARTON FOR REPAIR AND EVALUATION OF THIS
14 PROBLEM.

15 FACILITY STATUS E (28) | % POWER 100 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) OPERATOR OBSERVATION

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES: NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES: NUMBER 000 (40) | DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY (43): TYPE Z (42) | DESCRIPTION NA

8003110677

20 PUBLICITY: ISSUED N (44) | DESCRIPTION (45) NA

NRC USE ONLY

NAME OF PREPARER J. L. Rischling PHONE: 616-465-5901

GPO 917-926

86