DEC 0 6 1991

DCD(DCB) [illegible]

Docket No. 50-315
Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. E. E. Fitzpatrick
Vice President
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Dear Mr. Fitzpatrick:

This refers to the routine safety inspection conducted by J. A. Isom, T. G. Colburn, D. G. Passehl, E. R. Schweibinz, J. F. Harold and C. N. Orsini of this office from October 16 through November 26, 1991 of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and DPR-74, and to the discussion of our findings with A. A. Blind and others of your staff at the conclusion of the inspection. This refers also to a routine management meeting conducted at the plant site on November 22, 1991.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel. Items discussed at the management meeting are also summarized.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by W. D. Shafer

W. D. Shafer, Chief
Reactor Projects Branch 2

Enclosure:
Inspection Reports
No. 50-315/91025(DRP);
No. 50-316/91025(DRP)

See Attached Distribution YES

RIII	RIII	RIII
ERS	ERS	[illegible]
Schweibinz/dp	for Jorgensen	Shafer
12-6-91	12-6-91	12/6/91

9112160081 911206
PDR ADOCK 05000315
Q PDR

IE01
1/1

Distribution

cc w/enclosure:
A. A. Blind, Plant Manager
DCD/DCB (RIDS)
OC/LFDCB
Resident Inspector, RIII
James R. Padgett, Michigan Public
Service Commission
EIS Coordinator, USEPA
Region 5 Office
Michigan Department of
Public Health
D. C. Cook, LPM, NRR

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

DEC 0 6 1991

Docket No. 50-315
Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. E. E. Fitzpatrick
Vice President
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Dear Mr. Fitzpatrick:

This refers to the routine safety inspection conducted by J. A. Isom, T. G. Colburn, D. G. Passehl, E. R. Schweibinz, J. F. Harold and C. N. Orsini of this office from October 16 through November 26, 1991 of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and DPR-74, and to the discussion of our findings with A. A. Blind and others of your staff at the conclusion of the inspection. This refers also to a routine management meeting conducted at the plant site on November 22, 1991.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel. Items discussed at the management meeting are also summarized.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W D Shafer

W. D. Shafer, Chief
Reactor Projects Branch 2

Enclosure:
Inspection Reports
No. 50-315/91025(DRP);
No. 50-316/91025(DRP)

See Attached Distribution

Distribution

cc w/enclosure:
A. A. Blind, Plant Manager
DCD/DCB (RIDS)
OC/LFDCB
Resident Inspector, RIII
James R. Padgett, Michigan Public
Service Commission
EIS Coordinator, USEPA
Region 5 Office
Michigan Department of
Public Health
D. C. Cook, LPM, NRR