NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M I D C C 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
7 8 | 9 LICENSEE CODE 14 | 15 LICENSE NUMBER 25 | 26 LICENSE TYPE 30 | 57 CAT 58

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 1 5 (7) | 0 6 1 2 8 0 (8) | 0 7 1 0 8 0 (9)
7 8 | 60 61 DOCKET NUMBER 68 | 69 EVENT DATE 74 | 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 WHILE PERFORMING DIVIDER BARRIER SEAL INSPECTION PER STP.006, SEVERAL AREAS
03 OF THE DIVIDER SEAL WERE CRACKED AND SPLIT, CONSTITUTING AN INOPERABLE SEAL
04 PER T.S. 3.6.5.3. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. NO REDUN-
05 DANT SYSTEMS. PREVIOUS EVENTS 79-029/03L-0 AND FOR DOCKET NO. 05000316,
06 79-043/03X-1.
07
08 | 7 8 9 80

09 | SYSTEM CODE S B (11) | CAUSE CODE E (12) | CAUSE SUBCODE X (13) | COMPONENT CODE X X X X X X (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)
7 8 | 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 0 (21 22) | — (23) | SEQUENTIAL REPORT NO. 0 1 4 (24 26) | / (27) | OCCURRENCE CODE 0 3 (28 29) | REPORT TYPE L (30) | — (31) | REVISION NO. 0 (32)

ACTION TAKEN A (18) (33) | FUTURE ACTION F (19) (34) | EFFECT ON PLANT Z (20) (35) | SHUTDOWN METHOD Z (21) (36) | HOURS (22) 0 0 0 0 (37 40) | ATTACHMENT SUBMITTED N (23) (41) | NPRD-4 FORM SUB. N (24) (42) | PRIME COMP. SUPPLIER A (25) (43) | COMPONENT MANUFACTURER U 0 6 6 (26) (44 47)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 THE DEFECTIVE AREAS OF THE DIVIDER BARRIER SEAL ARE BEING REPLACED AND
11 WILL BE INSPECTED PRIOR TO UNIT HEATUP TO MODE 4. THE SPECIFIC CAUSE
12 FOR THE SEAL FAILURE COULD NOT BE DETERMINED. DESIGN CHANGE REQUEST
13 12-1766 HAS BEEN SUBMITTED TO INVESTIGATE ALTERNATE MATERIALS.
14 | 7 8 9 80

15 | FACILITY STATUS G (28) (9 10) | % POWER 0 0 0 (29) (10 12) | OTHER STATUS (30) N/A (13 44) | METHOD OF DISCOVERY B (31) (45 46) | DISCOVERY DESCRIPTION (32) SURVEILLANCE INSPECTION (46 80)

16 | ACTIVITY RELEASED Z (33) (9 10) | CONTENT OF RELEASE Z (34) (10 11) | AMOUNT OF ACTIVITY (35) N/A (11 44) | LOCATION OF RELEASE (36) N/A (45 80)

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) (9 11) | TYPE Z (38) (11 12) | DESCRIPTION (39) N/A (13 80)

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) (9 11) | DESCRIPTION (41) N/A (12 80)

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) (9 10) | DESCRIPTION (43) N/A (10 80) 8007150703

20 | PUBLICITY ISSUED N (44) (9 10) | DESCRIPTION (45) N/A (10 68) | NRC USE ONLY (69 80)

NAME OF PREPARER M. S. BROWN PHONE: (616) 465-5901, EXT.1398

GPO 917-926

5 Copies