SAFEGUARDS INFORMATION

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W.
ATLANTA, GEORGIA 30323

OCT 27 1988

Report Nos.: 50-250/88-31 and 50-251/88-31

Licensee: Florida Power and Light Company
9250 West Flagler Street
Miami, FL 33102

Docket Nos.: 50-250 and 50-251 License Nos.: DPR-31 and DPR-41

Facility Name: Turkey Point 3 and 4

Inspection Conducted: October 6-7, 1988

Inspector: D. H. Thompson for
Orysia Masnyk, Physical Security Specialist — Date Signed: 10-26-88

Approved by: D. R. McGuire
D. R. McGuire, Chief, Physical Security Section — Date Signed: 10/26/88
Nuclear Materials Safety and Safeguards Branch
Division of Radiation Safety and Safeguards

SUMMARY

Scope: This special, announced inspection was conducted in response to the licensee's report of a failure to control access to a vital area due to the incorrect placement of a compensatory post.

Results: In the areas inspected, two apparent violation of regulatory requirements were confirmed.

8811040012 881027
PDR ADOCK 05000250
Q PDC