ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8904200213 DOC.DATE: 89/04/11 NOTARIZED: NO DOCKET #
FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
AUTH.NAME AUTHOR AFFILIATION
EBNETER,S.D. Region 2, Ofc of the Director
RECIP.NAME RECIPIENT AFFILIATION
CONWAY,W.F. Florida Power & Light Co.

SUBJECT: Forwards Exam Rept 50-250/OL-89-01 administered during wks of 890313 & 20.

DISTRIBUTION CODE: IE42D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 24+58
TITLE: Operator Licensing Examination Reports

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL
	PD2-2 PD	1	1	EDISON,G	1	1
INTERNAL:	AEOD/DSP/TPAB	1	1	NRR SHANKMAN,S	1	1
	NRR/DLPQ/HFB 10	1	1	NRR/DLPQ/OLB 10	1	1
	NUDOCS-ABSTRACT	1	1	REG FILE 02	1	1
	RGN2 FILE 01	1	1			
EXTERNAL:	LPDR	1	1	NRC PDR	1	1
	NSIC	1	1			

R I D S / A D D S

R I D S / A D D S

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 12 ENCL 12

April 11, 1989

Florida Power and Light Company
ATTN: Mr. W. F. Conway
Senior Vice President
Nuclear Energy Department
P. O. Box 14000
Juno Beach, FL 33408

Gentlemen:

SUBJECT: TURKEY POINT REQUALIFICATION EXAMINATION REPORT - 50-250/OL-89-01

The NRC administered examinations during the weeks of March 13, 1989 and March 20, 1989, to employees of your company who currently hold licenses to operate the Turkey Point Nuclear Plant. At the conclusion of the site visit, preliminary findings were discussed with those members of your staff identified in the Examination Report, Enclosure 1.

A table summarizing the examination results for each examined individual is provided in Enclosure 2.

Copies of the written examination and answer key are included in this report as Enclosure 3.

A Requalification Program Evaluation Report is included as Enclosure 4. This Evaluation Report finds that the Turkey Point Requalification Program remains unsatisfactory. Your attention is invited to the findings in the Evaluation Report which indicate weaknesses in the areas of examination construction, and training and evaluation of licensed operators. As stated in Confirmation of Action Letter, 89-01, these areas must be addressed in a corrective action plan which is to be presented to the NRC by May 1, 1989.

A Simulator Fidelity Report is provided in this report as Enclosure 5.

In accordance with 10 CFR 2.790(a), a copy of this letter and Enclosures 1, 3, 4, and 5 will be placed in the NRC's Public Document Room. Enclosure 2 is exempt from public disclosure pursuant to 10 CFR 2.790(a) and will not be sent to the Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

(original signed by S. Ebneter)

Stewart D. Ebneter
Regional Administrator

Enclosures: (See Page 2)

8904200213 890411
PDR ADOCK 05000250
V PDC

IE42
1/1