NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A L B R F 2 (2)	0 0 - 0 0 0 0 0 - 0 0 (3)	4 1 1 1 1 (4)	(5)
		LICENSEE CODE	LICENSE NUMBER	LICENSE TYPE	CAT

CON'T

0 1	REPORT SOURCE	L (6)	0 5 0 0 0 2 6 0 (7)	0 6 0 5 7 9 (8)	0 7 0 3 7 9 (9)
			DOCKET NUMBER	EVENT DATE	REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation while performing SI 4.1.A-14, turbine first stage pressure
0 3 permissive, pressure switches PS-1-81A & B and PS-1-91A & B setpoints exceeded T. S.
0 4 Table 3.1.A limits by 3 to 8 psig. The problem would have inhibited reactor scram, on
0 5 a turbine trip, until reactor power was greater than 31 percent. TS limit is 30 percent.
0 6 Previous occurrence 50-259/7916. There was no hazard to the public health or safety.
0 7 There are no redundant channels.
0 8

0 9	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
	I A (11)	E (12)	E (13)	I N S T R U (14)	S (15)	Z (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	7 9	—	0 1 6	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
E (18)	X (19)	Z (20)	Z (21)	0 0 0 0	Y (23)	N (24)	N (25)	B 0 7 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The model B2T-A12SS switches had drifted. The switches were recalibrated and function-
1 1 ally tested satisfactorily. The cause of the instrument drift is still under inves-
1 2 tigation.
1 3
1 4

1 5	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
	E (28)	0 7 7 (29)	NA	B (31)	During surveillance testing

1 6	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

1 7	NUMBER	TYPE	DESCRIPTION (39)
	0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

1 8	NUMBER	DESCRIPTION (41)
	0 0 0 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

1 9	TYPE	DESCRIPTION
	Z (42)	NA

PUBLICITY

2 0	ISSUED	DESCRIPTION (45)	NRC USE ONLY
	N (44)	NA	

NAME OF PREPARER ______________________ PHONE: ______________________

7907090356