NRC FORM 366 (7-77)

Update Report - Previous Report -- 3-17-80

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

8005130615

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ALBRF2 (2) | 00-0000-00 (3) | 4 1 1 1 1 (4) | (5)

7 8 | 9 LICENSEE CODE 14 | 15 LICENSE NUMBER 25 | 26 LICENSE TYPE 30 | 57 CAT 58

CON'T

01 | REPORT SOURCE L (6) | 05000 26 0 (7) | 0 2 1 7 8 0 (8) | (9)

7 8 | 60 | 61 DOCKET NUMBER 68 | 69 EVENT DATE 74 | 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During hot shutdown 480 V RMOV Board 2B failed to transfer properly during manual

03 transfer. Board was immediately re-energized. Failure to transfer caused the

04 loss of RPS MG Set 2B. Reference Technical Specification 3.5.B.1 (2) and

05 3.5.A.1 (2) 480 V RMOV Boards 2A, 2C, and 2D were available. There was no

06 danger to health or safety of the public. No previous occurrences.

07

08

7 8 9 80

09 | SYSTEM CODE EB (11) | CAUSE CODE X (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE CKTBRK (14) | COMP. SUBCODE B (15) | VALVE SUBCODE Z (16)

7 8 | 9 10 | 11 | 12 | 13 18 | 19 | 20

(17) LER/RO REPORT NUMBER | EVENT YEAR 80 | — | SEQUENTIAL REPORT NO. 011 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 1

21 22 | 23 | 24 26 | 27 | 28 29 | 30 | 31 | 32

ACTION TAKEN X (18) | FUTURE ACTION X (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER Z (25) | COMPONENT MANUFACTURER Z999 (

33 | 34 | 35 | 36 | 37 40 | 41 | 42 | 43 | 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Investigation revealed board would transfer to alternate feed but not from

11 alternate to normal. This was caused by dirty moveable contacts on normal

12 breaker. Contacts were cleaned and board transferred properly. This is a

13 random failure. control will consist of scheduled breaker main-

14 tenance program presently scheduled once an operating cycle.

7 8 9 80

15 | FACILITY STATUS G (28) | % POWER 000 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observed

7 8 | 9 | 10 12 | 13 44 | 45 | 46 80

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

7 8 | 9 | 10 | 11 44 | 45 80

17 | PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

7 8 | 9 11 | 12 | 13 80

18 | PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) NA

7 8 | 9 11 | 12 80

19 | LOSS OF OR DAMAGE TO FACILITY (43) TYPE Z (42) | DESCRIPTION NA

7 8 | 9 | 10 80

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

7 8 | 9 | 10 68 | 69 80

NAME OF PREPARER PHONE: