NRC FORM 366 (7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NYNMP1 (2) | 00-0000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 | REPORT SOURCE L (6) | 05000227 (7) | 040179 (8) | 050179 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During periodic type C leakage test, found the following valves in
03 excess of Technical Specification: IV 68-06, IV 201-09, IV 201-10 and
04 IV 58.1-02. Repairs for these valves will be during this outage.
05
06
07
08

09 SYSTEM CODE SH (11) | CAUSE CODE E (12) | CAUSE SUBCODE X (13) | COMPONENT CODE VALVEX (14) | COMP. SUBCODE C (15) | VALVE SUBCODE C (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 79 | — | SEQUENTIAL REPORT NO. 005 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN B (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER A585 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Repairs will be completed during outage and the results of retest will
11 be included in Summary Report.
12
13
14

15 FACILITY STATUS H (28) | % POWER 000 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32)

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
17 NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES
18 NUMBER 000 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE Z (42) | DESCRIPTION NA

7905070411

PUBLICITY
20 ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

NAME OF PREPARER R. Jutras PHONE: 315-343-2110 Ext. 1327

GPO 917-926