NRC FORM 366 (7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	N J S G S 1 (2)	0 0 - 0 0 0 0 0 - 0 0 (3)	4 1 1 1 1 (4)	(5)
	LICENSEE CODE	LICENSE NUMBER	LICENSE TYPE	CAT

CON'T

0 1	REPORT SOURCE L (6)	0 5 0 0 0 2 7 2 (7)	0 1 0 3 7 9 (8)	0 1 3 1 7 9 (9)
		DOCKET NUMBER	EVENT DATE	REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation upon exiting containment, a leak rate test on
0 3 El. 100 air lock showed excessive leak rate. The Action Statement for
0 4 T/S 3.6.1.3 was implemented. The doors were reworked and the air lock
0 5 was returned to operation within 5 hours. This is the third occurrence
0 6 of this type (78-58, 78-80)
0 7
0 8

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
0 9	S A (11)	E (12)	X (13)	P E N E T R (14)	A (15)	Z (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	7 9	—	0 0 2	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
A (18)	D (19)	Z (20)	Z (21)	0 0 0 0	Y (23)	Y (24)	L (25)	C 3 1 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The inner and outer door seals failed due to a split at the vulcanized
1 1 seam. Both door seals were replaced and the air lock retested satis-
1 2 factorily. Design Change Request 1-ED-0442 has been submitted to up-
1 3 grade the air locks.
1 4

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	E (28)	1 0 0 (29)	N/A	C (31)	Air Leak Rate Test

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z (33)	Z (34)	N/A	N/A

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	Z (38)	N/A

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	N/A

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	N/A

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
2 0	Z (44)	N/A	

7902050201 NAME OF PREPARER A. W. Kapple PHONE: (609) 365-7000 Salem Ext. 628