NRC FORM 366 (7-77)

Update Report - Previous Report Date 10/26/78

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NJSGS1 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (7–14) LICENSE NUMBER (15–25) LICENSE TYPE (26–30) CAT (57–58)

CON'T 01 REPORT SOURCE | L (6) | 05000272 (7) | 092978 (8) | 032979 (9)
DOCKET NUMBER (60–68) EVENT DATE (69–74) REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, the Resident NRC Inspector identified a missing fire
03 barrier in a cable penetration. Inspection showed the fire barrier in place in the
04 identified penetration but an adjacent penetration was missing the fire barrier. A
05 fire watch was posted in accordance with T/S Action Statement 3.7.11a while repairs
06 were being made. This is the second occurrence of this type (78-48).
07
08

09 SYSTEM CODE ZZ (11) | CAUSE CODE D (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE PENETR (14) | COMP. SUBCODE D (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 78 | — | SEQUENTIAL REPORT NO. 067 | / | OCCURRENCE CODE 03 | REPORT TYPE X | — | REVISION NO. 1

ACTION TAKEN X (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER Z999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 This event was caused by failure of administrative controls to insure fire barrier
11 installation. The cable penetration was immediately sealed. All cable penetrations
12 on Unit No. 1 which require fire barriers have been inspected and discrepancies
13 corrected. Controls established for LER 78-48/03L shall provide adequate measures
14 to prevent reoccurrence.

15 FACILITY STATUS E (28) | % POWER 065 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY d (31) | DISCOVERY DESCRIPTION (32) NRC Resident Inspector

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

17 PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

18 PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) N/A

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) N/A

20 PUBLICITY ISSUED Z (44) | DESCRIPTION (45) N/A | NRC USE ONLY

NAME OF PREPARER A. W. Kapple PHONE: (609) 365-7000 Salem Ext. 628

7904030295