NRC FORM 366

U.S. NUCLEAR REGULATORY COMMISSION

IE MAIL / File

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

V A S P S 1 (2) 0 0 - 0 0 0 0 0 - 0 0 (3) 4 1 1 1 1 (4) | | (5)

LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

REPORT SOURCE L (6) 0 5 0 0 0 2 8 0 (7) 0 6 0 6 7 9 (8) | | | | | | (9)

DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

VEPCO has discovered abnormal degradation of cable insulation on Emergency Power System battery chargers in use at Surry Power Station. The affected chargers are made by C&D; Model ARC 130H/K200F3. This is reportable per T.S. 6.6.2.a.(9).

SYSTEM CODE (11) CAUSE CODE (12) CAUSE SUBCODE (13) COMPONENT CODE (14) COMP. SUBCODE (15) VALVE SUBCODE (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.

ACTION TAKEN (18) FUTURE ACTION (19) EFFECT ON PLANT (20) SHUTDOWN METHOD (21) HOURS (22) ATTACHMENT SUBMITTED (23) NPRD-4 FORM SUB. (24) PRIME COMP. SUPPLIER (25) COMPONENT MANUFACTURER (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The cause is unknown at this time. The manufacturer will be contacted.

FACILITY STATUS (28) % POWER 0 0 0 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32) Routine maintenance

ACTIVITY CONTENT: RELEASED OF RELEASE Z (33) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA CONTENT Z (34)

PERSONNEL EXPOSURES: NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION (39) NA

PERSONNEL INJURIES: NUMBER 0 0 0 (40) DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43): TYPE Z (42) DESCRIPTION NA

PUBLICITY: ISSUED N (44) DESCRIPTION (45) NA

NRC USE ONLY

J. P. O'REILLY
~~[illegible]~~
C. M. UPRIGHT
P. D. CHENDEMI
W. B. KENNA
F. J. LONG
~~C. E. MURPHY~~
B. T. SUTHERLAND
K. M. CLARK
Lewis
[illegible]

79 JUN 7 P3: 28
USNRC REGION II
ATLANTA, GEORGIA

W. T. Stewart (804) 357-3184

7906190399

A002 5 0/1