GEOCON
PROFESSIONAL SERVICES

U.S. NRC Region III
2443 Warrenville Road
Suite 210
Lisle, Illinois 60532-4352

Ms. Erin Kennedy

Health Physicist- Materials Licensing

Ms. Kennedy,

Below is the combined list of gauges (Make/Model/Serial Number) that will be on the Geocon Professional Services NRC License Number 12-32746-01;

1. Troxler	3430	19989
2. Troxler	3430	25821
3. Troxler	3430	25822
4. Troxler	3430	30009
5. Troxler	3440	30233
6. Troxler	3430	36447
7. Troxler	3430	36449
8. Troxler	3450	63782
9. Troxler	3440	67997
10. Troxler	3440	67998
11. Troxler	3440	69129
12. Troxler	3430	71222
13. Troxler	3430	71223
14. Troxler	3430	71224
15. Troxler	3430	71240
16. Troxler	3430	71432
17. Troxler	3430	71433

Geocon Professional Services is requesting a total possession limit be 20 Troxler 3400 series gauges on our license.

Below are the latest Leak Tests for the above listed gauges. This will cover all the gauges currently possessed by Geocon Professional Services under License 12-32746-01.

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

2/27/2019
Test Number: 6

DOUG JURY
GeoCon Service(FRANKFORT)
9370 W. LARAWAY RD, suite D
Frankfort, IL 60423

Phone: (815)523-7924
Fax: (815)464-8691

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3430
Gauge S/N: 19989

Test Date: 2/19/2019

Source (Model/Serial#)	Reading in microCuries
47-15473	0.00000
75-1202	0.00022

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: 02/27/2019

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

4/2/2019
Test Number: 7

DOUG JURY
GeoCon Service(FRANKFORT)
9370 W. LARAWAY RD, suite D
Frankfort, IL 60423

Phone: (815)523-7924
Fax: (815)464-8691

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3430
Gauge S/N: 25821

Test Date: 3/26/2019

Source (Model/Serial#)	Reading in microCuries
47-22199	0.00000
75-8804	0.00024

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: 04/02/2019

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

2/27/2019
Test Number: 8

DOUG JURY
GeoCon Service(FRANKFORT)
9370 W. LARAWAY RD, suite D
Frankfort, IL 60423

Phone: (815)523-7924
Fax: (815)464-8691

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3430
Gauge S/N: 25822

Test Date: 2/19/2019

Source (Model/Serial#)	Reading in microCuries
47-22200	0.00000
75-8805	0.00028

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: 02/27/2019

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

2/27/2019
Test Number: 4

DOUG JURY
GeoCon Service(FRANKFORT)
9370 W. LARAWAY RD, suite D
Frankfort, IL 60423

Phone: (815)523-7924
Fax: (815)464-8691

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3440
Gauge S/N: 30233

Test Date: 2/19/2019

Source (Model/Serial#)	Reading in microCuries
47-27212	0.00000
750-4484	0.00025

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: 02/27/2019

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

4/2/2019
Test Number: 5

DOUG JURY
GeoCon Professional Services, ll(FRANKFOR
9370 W. LARAWAY RD
FRANKFORT, IL 60423

Phone: (815)523-7924
Fax: (217)403-1559

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3430
Gauge S/N: 36447

Test Date: 3/26/2019

Source (Model/Serial#)	Reading in microCuries
78-1264	0.00001
77-3632	0.00028

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: 04/02/2019

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

4/2/2019
Test Number: 7

DOUG JURY
GeoCon Professional Services, ll(FRANKFOR
9370 W. LARAWAY RD
FRANKFORT, IL 60423

Phone: (815)523-7924
Fax: (217)403-1559

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3430
Gauge S/N: 36449

Test Date: 3/26/2019

Source (Model/Serial#)	Reading in microCuries
78-1266	0.00000
77-3634	0.00026

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: 04/02/2019

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

4/2/2019
Test Number: 5

DOUG JURY
GeoCon Service(FRANKFORT)
9370 W. LARAWAY RD, suite D
Frankfort, IL 60423

Phone: (815)523-7924
Fax: (815)464-8691

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3450
Gauge S/N: 63782

Test Date: 3/26/2019

Source (Model/Serial#)	Reading in microCuries
78-6364	0.00000
77-9945	0.00027

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: 04/02/2019

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

4/2/2019
Test Number: 5

DOUG JURY
GeoCon Service(FRANKFORT)
9370 W. LARAWAY RD, suite D
Frankfort, IL 60423

Phone: (815)523-7924
Fax: (815)464-8691

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3440
Gauge S/N: 67997

Test Date: 3/26/2019

Source (Model/Serial#)	Reading in microCuries
78-8755	0.00000
77-12768	0.00022

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: 04/02/2019

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

2/27/2019
Test Number: 7

DOUG JURY
GeoCon Service(FRANKFORT)
9370 W. LARAWAY RD, suite D
Frankfort, IL 60423

Phone: (815)523-7924
Fax: (815)464-8691

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3440
Gauge S/N: 67998

Test Date: 2/19/2019

Source (Model/Serial#)	Reading in microCuries
78-8756	0.00000
77-12769	0.00023

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: 02/27/2019

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

4/2/2019
Test Number: 3

DOUG JURY
GeoCon Professional Services, ll(FRANKFOR
9370 W. LARAWAY RD
FRANKFORT, IL 60423

Phone: (815)523-7924
Fax: (217)403-1559

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3440
Gauge S/N: 69129

Test Date: 3/26/2019

Source (Model/Serial#)	Reading in microCuries
47-25357	0.00000
77-13554	0.00023

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: 4/02/2019

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

10/9/2018
Test Number: 1

DOUG JURY
GeoCon Service(FRANKFORT)
9370 W. LARAWAY RD, suite D
Frankfort, IL 60423

Phone: (815)523-7924
Fax: (815)464-8691

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3430
Gauge S/N: 71222

Test Date: 10/4/2018

Source (Model/Serial#)	Reading in microCuries
78-10484	0.00000
77-14094	0.00023

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: 10/09/2018

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

10/9/2018
Test Number: 1

DOUG JURY
GeoCon Service(FRANKFORT)
9370 W. LARAWAY RD, suite D
Frankfort, IL 60423

Phone: (815)523-7924
Fax: (815)464-8691

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3430
Gauge S/N: 71223

Test Date: 10/4/2018

Source (Model/Serial#)	Reading in microCuries
78-10485	0.00000
77-14095	0.00025

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: _____

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

T-1

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

9/19/2018
Test Number: 1

DOUG JURY
GeoCon Service(FRANKFORT)
9370 W. LARAWAY RD, suite D
Frankfort, IL 60423

Phone: (815)523-7924
Fax: (815)464-8691

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3430
Gauge S/N: 71224

Test Date: 9/14/2018

Source (Model/Serial#)	Reading in microCuries
78-10486	0.00000
77-14906	0.00024

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: 09/19/2018

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

10/9/2018
Test Number: 1

DOUG JURY
GeoCon Service(FRANKFORT)
9370 W. LARAWAY RD, suite D
Frankfort, IL 60423

Phone: (815)523-7924
Fax: (815)464-8691

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3430
Gauge S/N: 71240

Test Date: 10/4/2018

Source (Model/Serial#)	Reading in microCuries
78-10489	0.00000
77-14911	0.00028

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: 10/09/2018

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

T-14

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

9/19/2018
Test Number: I

DOUG JURY
GeoCon Service(FRANKFORT)
9370 W. LARAWAY RD
Frankfort, IL 60423

Phone: (815)523-7924
Fax: (815)464-8691

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3430
Gauge S/N: 71432

Test Date: 9/14/2018

Source (Model/Serial#)	Reading in microCuries
78-10592	0.00000
77-15029	0.00021

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.* The source(s) tested above may remain in use.

Reviewed by: _____ Date: 09/19/2018

Customer Signature: _____ Date: _____

*CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.

InstroTek, Inc.
1 Triangle Drive, PO Box 13944
Research Triangle Park, NC 27709
(919)875-8371 Fax (919)875-8328

10/9/2018
Test Number: 1

DOUG JURY
GeoCon Service(FRANKFORT)
9370 W. LARAWAY RD, suite D
Frankfort, IL 60423

Phone: (815)523-7924
Fax: (815)464-8691

LEAK TEST CERTIFICATE

NC Materials License #092-1073-1

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removable contamination.

Gauge Model: 3430
Gauge S/N: 71433

Test Date: 10/4/2018

Source (Model/Serial#)	Reading in microCuries
78-10593	0.00000
77-15030	0.00030

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source.° The source(s) tested above may remain in use.

Reviewed by: _____ Date: 10/09/2018

Customer Signature: _____ Date: _____

°CPN gauges are 50 mCi Am241:Be and 10 mCi Cs-137. Humboldt gauges are 40 mCi Am241:Be and 10 mCi Cs-137. InstroTek Gauge is 40 mCi Am241:Be and 10 mCi Cs-137. Troxler gauges all, except 4640, are 40 mCi Am241:Be and 8 mCi Cs-137. Troxler 4640 is 8 mCi Cs-137.



Douglas R. Jury

Radiation Safety Officer

Geocon Professional Services

O-815-523-7924

C-815-509-3629

djury@geoconcompanies.com

Song, Taehoon

From: Kennedy, Erin
Sent: Friday, April 19, 2019 9:03 AM
To: Song, Taehoon; Sandrik, Lauren; Pavon, Sandy
Cc: Tomczak, Tammy
Subject: FW: RE: Additional Information Needed to Amend NRC Lic. No. 12-32746-01
Attachments: Geocon Response Document - Form 699 response 190417.pdf

Good Morning!

Will you please add the attached document to ADAMS?

Licensee: GEOCON Professional Services

LN: 12-32746-01
DN:030-38021
CN: 611240

Thank you!

Erin

From: Doug Jury [mailto:djury@geoconcompanies.com]
Sent: Wednesday, April 17, 2019 10:20 AM
To: Kennedy, Erin <Erin.Kennedy@nrc.gov>
Subject: [External_Sender] RE: Additional Information Needed to Amend NRC Lic. No. 12-32746-01

Erin,

Attached is the response to your request as stated in the 699 form. Please contact me with any issues with the attached. Thank you.

Douglas R. Jury
GEOCON PROFESSIONAL SERVICES
O 815-523-7924
C 815-509-3629
djury@geoconcompanies.com

From: Kennedy, Erin <Erin.Kennedy@nrc.gov>
Sent: Thursday, April 11, 2019 1:26 PM
To: Doug Jury <djury@geoconcompanies.com>; Nick Lococo <nick.lococo@geoconcompanies.com>
Subject: Additional Information Needed to Amend NRC Lic. No. 12-32746-01

Good Afternoon Mr. Jury,

Thank you for taking the time to discuss the amendment of your NRC license with me this morning. Please see the attached conversation record for further details. If you have any questions, I will be available at 630-829-9876.

Thank you,

Erin Kennedy
U.S. Nuclear Regulatory Commission, Region III
Health Physicist- Materials Licensing
Email: erin.kennedy@nrc.gov
Office: 630-829-9876

This e-mail is intended for the use of the individual to whom it is addressed. The message may contain information that is privileged, confidential, and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. Please notify the sender of this e-mail by reply if you have received this message in error. Further, GEOCON Professional Services makes no representation as to the long term compatibility, usability, or readability of any attached digital or electronic file.