NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ARANO1 (2) | 00-000-00 (3) | 4111 (4) | (5)
LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T
01 | REPORT SOURCE L (6) | 050003 (7) DOCKET NUMBER | 081079 (8) EVENT DATE | 081779 (9) REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During Cold Shutdown operation, Leak Rate Testing of Reactor Building
03 penetration V-1, per procedure 1304.23, revealed a leak rate in excess
04 of 50,000 cc/min. It was determined to be caused by the outside iso-
05 lation valve, CV-7402. The inside isolation valve, CV-7404, did not
06 leak.
07 This occurrence is similar to LER 50-313/79-005 and 77-15. Reportable
08 per T.S. 6.12.3.2b.

09 | SYSTEM CODE AD (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE VALVEX (14) | COMP SUBCODE E (15) | VALVE SUBCODE D (16)

(17) LER RO REPORT NUMBER | EVENT YEAR 79 | — | SEQUENTIAL REPORT NO. 012 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO 0

ACTION TAKEN E (18) | FUTURE ACTION G (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB Y (24) | PRIME COMP SUPPLIER A (25) | COMPONENT MANUFACTURER P340 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Investigation revealed that the valve required an adjustment of its
11 shims on the valve seat to match the surface of the butterfly. Adjust-
12 ments were made and the leak rate retested, meeting the 60% LA require-
13 ment of T.S.4.4.1.2.3. Test frequency increased from quarterly to
14 after every R.B. purge.

15 | FACILITY STATUS D (28) | % POWER 000 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance Test per T.S.4.4.1

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 | PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 | PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) NA

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION NA

956325

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA

7909170466

NRC USE ONLY

NAME OF PREPARER Chris N. Shively PHONE 501/968-2519