NRC FORM 366 (7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | C T M N S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)

LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T 01 | REPORT SOURCE L (6) | 0 5 0 0 0 2 4 5 (7) | 1 0 0 9 7 9 (8) | 1 1 0 8 7 9 (9)

DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On October 9, 1979, at 1545 hours, the emergency diesel generator was administratively
03 removed from service. While conducting inspections per NRC Bulletin 79-14, it was
04 discovered that 2 diesel service water piping restraints had not been installed
05 during original construction. No probable consequences occurred since Technical
06 Specifications allow emergency power sources to be conditionally removed from
07 service.
08

09 | SYSTEM CODE E E (11) | CAUSE CODE B (12) | CAUSE SUBCODE C (13) | COMPONENT CODE S U P O R T (14) | COMP. SUBCODE B (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER | EVENT YEAR 7 9 | — | SEQUENTIAL REPORT NO. 0 3 0 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN F (18) | FUTURE ACTION X (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER E 0 6 5 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The diesel generator was administratively declared inoperable for approximately
11 52 hours while temporary piping restraints were fabricated, installed and
12 certified. Further information is contained in unit response to NRC Bulletin 79-14.
13
14

15 | FACILITY STATUS E (28) | % POWER 1 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY C (31) | DISCOVERY DESCRIPTION (32) NRC 79-14 inspection

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES

17 | NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES

18 | NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

1729 268

LOSS OF OR DAMAGE TO FACILITY (43)

19 | TYPE Z (42) | DESCRIPTION NA

PUBLICITY

20 | ISSUED Z (44) | DESCRIPTION (45) NA

7911140 238

NRC USE ONLY

Ralph H. Young

203-447-1792 X-475