POOR ORIGINAL

NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 CARSS1 (2) 00-000-00 (3) 4 1 1 1 1 (4) (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 REPORT SOURCE L (6) 05000312 (7) 103179 (8) 111679 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While performing the requirements of I&E Bulletin 79-14, the District
03 contracted the A/E to assist in review and analysis. On 10/31/79,
04 the A/E informed the District that the as-built configuration of
05 Line 47360-10" HE2, when seismically reanalyzed, resulted in probable
06 support pipe overstresses.
07
08

09 SYSTEM CODE CJ (11) CAUSE CODE B (12) CAUSE SUBCODE A (13) COMPONENT CODE SUPORT (14) COMP SUBCODE B (15) VALVE SUBCODE Z (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 79 — SEQUENTIAL REPORT NO. 015 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN F (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS 0000 (22) ATTACHMENT SUBMITTED Y (23) NPRD-4 FORM SUB N (24) PRIME COMP SUPPLIER A (25) COMPONENT MANUFACTURER B130 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Design documentation and construction drawings were not in complete
11 conformance with the original seismic analyses. One new support was
12 installed and two support modifications were completed to correct the
13 discrepancy.
14

15 FACILITY STATUS E (28) % POWER 100 (29) OTHER STATUS (30) N/A — METHOD OF DISCOVERY D (31) DISCOVERY DESCRIPTION (32) Notification from A/E

16 ACTIVITY RELEASED Z (33) CONTENT OF RELEASE Z (34) AMOUNT OF ACTIVITY (35) N/A — LOCATION OF RELEASE (36) N/A

17 PERSONNEL EXPOSURES NUMBER 000 (37) TYPE Z (38) DESCRIPTION (39) N/A

18 PERSONNEL INJURIES NUMBER 000 (40) DESCRIPTION (41) N/A

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION (43) N/A

20 PUBLICITY ISSUED N (44) DESCRIPTION (45) N/A

NRC USE ONLY

1398 072

NAME OF PREPARER R. W. Colombo PHONE 916-452-3211

7911270

442