CENTRAL FILES

Metropolitan Edison Company
Post Office Box 480
Middletown, Pennsylvania 17057
717 944 1041

December 11, 1978

Mr. Boyce H. Grier
Director of Regulatory Operations
Region I
Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Operating License: DPR-73
Docket 50-320

Subject: REPORTABLE OCCURRENCE NO. 78-71/1P

Dear Mr. Grier:

This telegram is to confirm the telecon between Mr. G.A. Kunder, Unit II Superintendent Technical Support, and Mr. D. Haverkamp, Region I NRC at 15:30 hours on December 8, 1978.

A situation considered reportable under Technical Specification 6.9.1.8.I was discovered at 1400 on December 8, 1978, when the TMI-2 Architect Engineer determined a control logic discrepancy exists for the Make-up (HPI) pumps.

It was determined that the Control Logic allows two Make-up pumps to start on a Diesel Generator after loss of offsite power. Administrative Controls for the Make-up pumps are being exercised to prevent two Make-up pumps from automatically starting on one Diesel Generator until a modification can be installed.

Further details and corrective action will be discussed in the followup report.

Very truly yours,

G.A. Kunder
Unit II Superintendent/
Technical Support

GAK:bll

7812290093

A0 4
G1

-8 079