PSEG

Public Service Electric and Gas Company P.O. Box 168 Hancocks Bridge, New Jersey 08038

Salem Nuclear Generating Station

June 15, 1979

Mr. Boyce H. Grier
Director of USNRC
Office of Inspection and Enforcement
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Sir:

REPORTABLE OCCURRENCE 79-46/01P
SALEM NO. 1 UNIT LER

This letter will serve to confirm our verbal report to Mr. Leif Norrholm, the Salem NRC Resident Inspector, at the Region I office on June 14, 1979, advising of a reportable occurrence in accordance with Technical Specification 6.9.1.8.

Radiographic inspection of our No. 13 steam generator feed nozzle to pipe weld revealed a linear indication approximately 5 inches in length.

Notification of this apparent indication has been made to Public Service Engineering and Construction Department requesting further evaluation and subsequent verification of this indiction.

A detailed report will be submitted in the time period specified by the Technical Specifications.

Very truly yours,

H. J. Midura

H. J. Midura
Manager - Salem Generating Station

AWK:lds

CC: General Manager - Electric Production
Manager - Quality Assurance

311 133

7907090 213