Update Report - Previous Report Date 6/12/79

NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ARANO2 (2) | 00-000-000 (3) | 4111 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 05000368 (7) | 051479 (8) | 070679 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During Mode 3 operation, while utilizing the steam driven
03 Emergency Feedwater Pump, 2P7A, for normal auxiliary
04 feed, supply valves, 2CV-1039-2 and 2CV-1076-2, to
05 Steam Generator, 2E24B, would not respond to a Control
06 Room demand signal. The 2P7A feedwater loop to 2E24B
07 was declared inoperable. This occurrence is similar to
08 50-368/79-026. Reportable per T.S.6.9.1.9 (b).

09 SYSTEM CODE WB (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE VALVOP (14) | COMP SUBCODE A (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 79 | — | SEQUENTIAL REPORT NO. 037 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO 1

ACTION TAKEN B (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB N (24) | PRIME COMP SUPPLIER N (25) | COMPONENT MANUFACTURER E299 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Unit was placed in Mode 5 operation, due to an unrelated
11 problem, meeting the requirements of Action Statement
12 T.S.3.7.1.2. Investigation revealed a blown fuse in the
13 2CV-1039-2 circuitry and a stuck relay overriding the
14 2CV-1076-2 operation. Repairs were made & valves proven operable.

15 FACILITY STATUS B (28) | % POWER 000 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) NA

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
17 NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES
18 NUMBER 000 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY
19 TYPE Z (42) | DESCRIPTION (43) NA

PUBLICITY
20 ISSUED (44) | DESCRIPTION (45)

NRC USE ONLY

NAME OF PREPARER Chris Shively PHONE 501/968-2519

567 207

7907120,660