NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M D C C N 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 1 8 (7) | 0 6 1 9 7 9 (8) | 0 7 1 9 7 9 (9)
DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 2315 the Unit 2 containment gaseous and particulate radioactivity monitoring
03 systems failed due to a loss of the sampling pump (T.S.3.4.6.1.). The pump was
04 restarted at 0001 6/20/79, returning the gaseous and particulate radioactivity
05 monitoring systems to service. The containment sump level alarm system remained
06 operable during the event.
07
08

09 SYSTEM CODE B B (11) | CAUSE CODE X (12) | CAUSE SUBCODE X (13) | COMPONENT CODE Z Z Z Z Z Z (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 | — | SEQUENTIAL REPORT NO. 0 2 2 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN Z (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER Z (25) | COMPONENT MANUFACTURER Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 As stated above, pump was restarted approximately 45 minutes after it stopped; no
11 specific maintenance action had been taken to determine or correct the cause of the
12 failure. It is supposed that a spurious high flow signal occurred causing the running
13 pump to trip and preventing the backup pump from starting. Since the exact initiating
14 event could not be duplicated, no further maintenance action could be taken.

15 FACILITY STATUS E (28) | % POWER 1 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
17 NUMBER Z Z Z (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES
18 NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE Z (42) | DESCRIPTION NA

7907250304

PUBLICITY
20 ISSUED N (44) | DESCRIPTION (45) NA

510 004

NRC USE ONLY

NAME OF PREPARER S. M. Davis/J. S. Lagiewski PHONE: (301) 234-7942

GPO 917-926