LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N C B E P 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE X (6) | 0 5 0 - 0 3 2 5 (7) | 0 7 0 6 7 9 (8) | 0 8 0 2 7 9 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While conducting an as built inspection and analysis of supports and hangers on safety-
03 related lines, resulting from IE Bulletin 79-07, the support beams for snubber
04 1E11-49SS334, "B" RHR heat exchanger steam condensing line, were not capable of
05 carrying the calculated loads under worst case seismic conditions.
06 Technical Specification 3.7.5, 6.9.1.9b
07
08

09 | SYSTEM CODE C F (11) | CAUSE CODE B (12) | CAUSE SUBCODE A (13) | COMPONENT CODE S U P O R T (14) | COMP. SUBCODE B (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 — SEQUENTIAL REPORT NO. 0 4 2 — OCCURRENCE CODE 0 3 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN F (18) | FUTURE ACTION X (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0 0 0 0 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER U 0 8 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The support beams were reinforced as per UE&C redesign and plant modification 79-123.
11 The reanalysis of all safety-related lines listed in the final report will be continued
12 to determine if any other supports need modification. All supports requiring modifica-
13 tion will be modified in accordance with the FSAR and Technical Specification.
14

15 | FACILITY STATUS E (28) | % POWER 0 4 3 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY D (31) | DISCOVERY DESCRIPTION (32) A/E

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

POOR ORIGINAL

790806054 5

G0124

NAME OF PREPARER A. C. Tollison, Jr. PHONE: 919-457-9521