NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | C A R S S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT 58

CON'T 01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 1 2 (7) | 0 7 2 0 7 9 (8) | 0 8 0 2 7 9 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, analysis of the "Pipe Support Base Plate Design
03 Using Concrete Expansion Anchor Bolts" indicated six safety-related
04 anchors at Rancho Seco did not meet I.E. Bulletin 79-02 criteria No. 2.
05 This determined both Decay Heat Systems to be below the Limiting Conditions
06 for Operation, T.S. 3.3.2. The unit was taken to a HSD condition until
07 repairs were effected.
08

09 SYSTEM CODE C F (11) | CAUSE CODE B (12) | CAUSE SUBCODE A (13) | COMPONENT CODE S U P O R T (14) | COMP. SUBCODE B (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 | — | SEQUENTIAL REPORT NO. 0 0 7 | / | OCCURRENCE CODE 0 1 | REPORT TYPE T | — | REVISION NO. 0

ACTION TAKEN F (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT A (20) | SHUTDOWN METHOD A (21) | HOURS (22) 0 0 5 4 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER B 1 3 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 New design basis criteria presently utilized differs from that criteria
11 in effect during plant construction. The unit was shut down and the pipe
12 Supports were modified to meet the new criteria.
13
14

FACILITY STATUS E (28) | % POWER 1 0 0 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY D (31) | DISCOVERY DESCRIPTION (32) NRC IE Bulletin 79-02 Analysis

ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A

LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) N/A

PUBLICITY ISSUED Y (44) | DESCRIPTION (45) Local newspaper and wire service 7-20-79.

NRC USE ONLY

536 351

NAME OF PREPARER R. W. Colombo PHONE: (916) 452-3211

7908100482