TIC

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76012

June 4, 1979

In Reply Refer To:
Docket No. 50-267

Public Service Company of Colorado
ATTN: C. K. Millen,
Senior Vice President
P. O. Box 840
Denver, Colorado 80201

Gentlemen:

Reference your letter of May 8, 1979, P-79099, regarding the shock suppressors installed at Fort St. Vrain. We concur with your request for time to ascertain the exact nature of the problems with the shock suppressors prior to submitting a reportable occurrence report. However, when you have determined the nature of the problem or have completed your testing and repair program, the reportable occurrence report should be promptly submitted.

Sincerely,

G. L. Madsen, Chief,
Reactor Operations and
Nuclear Support Branch

cc:
D. W. Warembourg, Nuclear
Production Manager
Fort St. Vrain Nuclear Station
P. O. Box 368
Platteville, Colorado 80651

L. Brey, Quality Assurance
(Same Address)

501 021

7908080 442