7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | G A E I H 1 (2) | 0 0 0 0 0 0 0 0 0 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 2 1 (7) | 0 8 0 3 7 8 (8) | 0 8 1 7 7 9 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing HNP-1-3153 (LPCI Logic System Functional Test) time delay relay
0 3 E11-K70B was found to be set at 11 seconds which exceeds the limit set forth in Tech
0 4 Specs of 10± .5 seconds. The E11-K70B relay is used for load sequencing the RHR pump
0 5 2B onto the Emergency Power Bus following a loss of offsite power and a loss of cool-
0 6 ant accident. Similar relays E11-K70A, K75A, and B for the redundant pumps were
0 7 tested and proven operable per the LPCI LSFT mentioned above. This is a non-repetit-
0 8 ive occurrence for this relay.

0 9 SYSTEM CODE C F (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE R E L A Y X (14) | COMP. SUBCODE H (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 | — | SEQUENTIAL REPORT NO. 0 5 8 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN E (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER G 0 8 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The event was attributed to time delay relay set point drift. The relay was recalib-
1 1 rated to 10 seconds and tested.
1 2
1 3

POOR ORIGINAL

FACILITY STATUS H (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY Z (31) | DISCOVERY DESCRIPTION (32) N/A

ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A

827 128

LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) N/A

7908240486

PUBLICITY ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY

NAME OF PREPARER C. L. Coggin, Supt. Plt. Eng. Serv. PHONE 912-367-7781