TOLEDO EDISON

L79-1075
FILE: RR 2 (NP-32-79-11)

October 25, 1979

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 79-096
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: October 15, 1979

Enclosed are three copies of Licensee Event Report 79-096 and a supplemental information sheet which is being submitted in accordance with Technical Specification 6.9 to provide 14 day wri n notification of the subject occurrence.

Yours truly,

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/SNB/ljk

Enclosure

cc: Dr. Ernst Volgenau, Director
Office of Inspection and Enforcement
Encl: 40 copies LER 79-096

Mr. William G. McDonald, Director
Office of Management Information
and Program Control
Encl: 3 copies LER 79-096
2 copies telecopy report

1214 351

7910310299