# LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ALJMF1 (2) | 00-000 00-00 (3) | 41111 (4) | (5)
LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T 01 | REPORT SOURCE L (6) | 05000348 (7) | 122279 (8) | 012530 (9)
DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 0850 on 12-22-79, the River Water B train pumps were declared inoperable due to a
03 faulty level switch (Q5P25L5510). Tech. Spec. 3.7.5 requires both R.W. loops to be
04 operable. Tech Spec. 3.7.5 action statement requirements were met. The pumps were
05 returned to service at 1942 on 12-22-79. A similar occurence was reported in LER 79-
06 041/03L-0. The health/safety of the public were not affected.
07
08

09 SYSTEM CODE WE (11) | CAUSE CODE E (12) | CAUSE SUBCODE X (13) | COMPONENT CODE REAYX (14) | COMP. SUBCODE K (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 79 | — | SEQUENTIAL REPORT NO. 067 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION X (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER G050 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Moisture had entered the switch thereby making its operation erratic ie. R.W. pumps
11 4 and 5 would spuriously trip. The switch was replaced. Corrective action to prevent
12 moisture entry into the switch is being evaluated. A revision to this LER will be
13 submitted.
14

15 FACILITY STATUS E (28) | % POWER 100 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) R.W. pumps in tripped condition

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
17 NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES
18 NUMBER 000 (40) | DESCRIPTION (41) NA 1866 142

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE Z (42) | DESCRIPTION NA

PUBLICITY
20 ISSUED N (44) | DESCRIPTION (45) NA 8002040469 | NRC USE ONLY

NAME OF PREPARER W. G. Hairston III PHONE: (205) 899-5156