NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N C B E P 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | | (5)

LICENSEE CODE · LICENSE NUMBER · LICENSE TYPE · CAT

CON'T 0 1 | REPORT SOURCE L (6) | 0 5 0 - 0 3 2 5 (7) | 1 2 0 6 7 9 [illegible] | 0 1 2 9 8 0 [illegible]

DOCKET NUMBER · EVENT DATE · REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing PT 9.5, HPCI 1000# Flow Rate Test, the HPCI system isolated due to

0 3 a high suction pressure signal from 1E41-PSH-N031 which tripped the HPCI turbine

0 4 stop valve.

0 5

0 6

0 7

0 8 Technical Specifications 3.5.1, 6.9.1.9b

0 9

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
S F (11)	E (12)	B (13)	I N S T R U (14)	E (15)	Z (16)

(17) LER/RO REPORT NUMBER

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
7 9	—	1 0 4	/	0 3	L	—	1

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
B (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	Y (24)	N (25)	B 0 6 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The diaphragm on 1E41-PSH-N031 was found to be leaking, thus providing a false high

1 1 pressure signal. The diaphragm was replaced and returned to service satisfactorily.

1 2 This switch is checked on a quarterly basis per the calibration program. This is

1 3 considered an isolated event and no further action is required.

1 4

1 5 FACILITY STATUS C (28) | % POWER 0 1 3 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Periodic Test

1 6 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES

1 7 NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES

1 8 NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

1928 236

LOSS OF OR DAMAGE TO FACILITY (43)

1 9 TYPE Z (42) | DESCRIPTION NA

PUBLICITY

2 0 ISSUED N (44) | DESCRIPTION (45) NA

8002060 534

NRC USE ONLY

NAME OF PREPARER A. C. Tollison, Jr. PHONE: 919-457-9521