U. S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

REGION I

Report No. 70-820/79-14

Category UR

Docket No. 70-820 License No. SNM-777 Safeguards Group 1

Licensee: United Nuclear Corporation
Fuel Recovery Operation
Wood River Junction, RI 02894

Facility Name: United Nuclear Corporation

Inspection At: Wood River Junction, RI

Inspection Conducted: July 10-13, 1979

Date of Last Physical Security Inspection Visit: April 24-27, 1979

Type of Inspection: Unannounced Physical Security

Inspectors: M. Rogers, Physical Security Inspector — 10/18/79 date

For R. Ladun, Physical Security Inspector — 10/18/79 date

R. Rosano, Physical Security Inspector — 10/18/79 date

Approved by: J. W. Devlin, Chief, Security and Investigation Section, Safeguards Branch — 10/16/79 date

Inspection Summary:
Areas Inspected: Security Plan; Security Organization; Physical Barriers; Access Controls; Lock, Keys and Combinations; Detection Aids; Response Controls; Central Alarm and Communications Systems; Testing and Maintenance; SNM Protection; and Records and Reports.
Results: Of the nine areas inspected, no apparent items of noncompliance were identified. The inspection was initiated during regular hours and involved 56 inspector-hours by two regional and one headquarters based inspectors.

1517 253

Region I Form 167
(August 1979)

C 7912100057