NRC FORM 366
(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N C B E P 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)

LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T

0 1 | REPORT SOURCE L (6) | 0 5 0 - 0 3 2 5 (7) | 1 2 0 5 7 9 (8) | 1 2 2 8 7 9 (9)

DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing PT 2.1.7PC, HPCI Exhaust Diaphragm High Pressure Calibration,

0 3 | pressure switch 1E41-PS-N012A would not actuate at any applied pressure up to

0 4 | 30 psig. The desired setpoint is 7 + 0.7 psig increasing and the report limit is

0 5 | > 10 psig.

0 6 |

0 7 |

0 8 | Technical Specifications 3.3.2, 6.9.1.9b

0 9 | SYSTEM CODE: S F (11) | CAUSE CODE: E (12) | CAUSE SUBCODE: G (13) | COMPONENT CODE: I N S T R U (14) | COMP. SUBCODE: S (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 | — | SEQUENTIAL REPORT NO. 1 0 1 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN C (18) | FUTURE ACTION X (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER B 0 6 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Intermittent actuation of the internal micro switch was determined the cause for the

1 1 | switch failure. The switch was replaced and the calibration PT was completed

1 2 | successfully. This is considered an isolated event and no further action is required.

1 3 |

1 4 |

1 5 | FACILITY STATUS E (28) | % POWER 0 5 5 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Periodic Test

1 6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

1 7 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

1 8 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

1703 002

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

8001080 392

2 0 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

NAME OF PREPARER A. C. Tollison, Jr. PHONE 919-457-9521