MATERIAL TRANSMITTED HEREWITH
CONTAINS 2.790 INFORMATION

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

DEC 14 1979

Report No. 70-1115/79-16

Docket No. 70-1151 License No. SNM-1107

Safeguards Group III

Licensee: Westinghouse Electric Corporation
Nuclear Fuel Division
Drawer R
Columbia, South Carolina 29205

Facility Name: Westinghouse NFD

Inspection at: Columbia, South Columbia

Inspection Conducted: October 23 and 26-30, and November 2, 1979

Date of Last Material Control and Accounting Inspection Visit: August 21-24, 1979

Type of Inspection: Announced Material Control & Accounting

Inspectors: J. W. Bates, Chemist — Date Signed 12/13/79

P. W. Steele, Chemist — Date Signed 12/13/79

Approved by: F. P. Gillespie, Chief, MC&A Section, Safeguards Branch — Date Signed 12/13/79

Inspection Summary

Areas Inspected: Physical inventory procedures and follow-up on items of non-compliance and unresolved item.

The inspection involved 67 inspector-hours on site by two NRC inspectors and was begun during the regular hours.

Results: The licensee was found to be in compliance with NRC requirements in the two areas examined during the inspection except for the following two items:

1. Deficiency - Failure to follow the written procedure for determining holdup in process equipment (79-16-01) - This is a repeat item of noncompliance.

2. Deficiency - Failure to verify bulk volume measurement systems once each material balance period by inspection to determine damage, sediment build-up or other conditions that could cause a change in volume (79-16-02).

1940 213

MATERIAL TRANSMITTED HEREWITH
CONTAINS 2.790 INFORMATION

S-F2 79 - 114P
Copy ____ of ____ Copies
15 Pages
This Document is not to be reproduced without specific approval of IE:II

548

8002110