TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

February 4, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNIT 1 - INCORRECT VALVE DATA USED IN PIPING ANALYSES OF LINES PENETRATING THE STEEL CONTAINMENT VESSEL - NCR CEB 80-2 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector W. T. Cottle on January 4, 1980, in accordance with 10 CFR 50.55(e). Enclosed is our final report.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure
cc: Mr. Victor Stello, Jr., Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
S2
1/1

An Equal Opportunity Employer

8002140349