CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | G A E I H 1 (2) | 0 0 0 0 0 0 0 0 0 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

IN'T
1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 2 1 (7) | 0 1 1 4 7 9 (8) | 0 1 3 1 7 9 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 DURING NORMAL OPERATION, A HI-FLOW ALARM OCCURRED ON THE STACK EFFLUENT RADIATION
3 MONITOR. AN INVESTIGATION REVEALED THAT THE SAMPLE PUMP WAS NOT RUNNING. ATTEMPTS TO
4 RE-START THE PUMP WAS UNSUCCESSFUL. AN ATTEMPT TO START THE SPARE ALSO FAILED.
5 TO COMPLY WITH E.T.S. PARAGRAPH 2.1.4.b,a DAILY GRAB SAMPLE WAS TAKEN AND ANALYZED.
6 THE PUMPS WERE REPAIRED AND RETURNED TO SERVICE WITHIN 12 HOURS AFTER THE EVENT. THERE
7 WERE NO ILL EFFECTS UPON THE PUBLIC HEALTH AND SAFETY.
8

9 | SYSTEM CODE M C (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE P U M P X X (14) | COMP. SUBCODE H (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 — SEQUENTIAL REPORT NO. 0 0 3 — OCCURRENCE CODE 0 3 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN B (18) | FUTURE ACTION G (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER G 0 4 6 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 THE CARBON VANES IN THE PUMP IN OPERATION FAILED. THE SPARE PUMP FAILED TO START DUE
11 TO CONDENSED WATER SWELLING THE CARBON VANES AND STALLING THE PUMP. THE VANES IN BOTH
12 PUMPS WERE REPLACED. THE PUMPS WILL BE ROTATED IN OPERATION MORE FREQUENTLY TO ASSURE
13 SPARE PUMP RELIABILITY.
14

FACILITY STATUS E (28) | % POWER 0 8 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) OPERATOR OBSERVED ALARM

ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES: NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES: NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY: TYPE Z (42) | DESCRIPTION NA

790206 0298

PUBLICITY: ISSUED N (44) | DESCRIPTION (45) NA

NRC USE ONLY

NAME OF PREPARER W. H. ROGERS HEALTH PHYSICIST RADIOCHEMIST PHONE 912-367-7781

GPO 817-928