NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

February 2, 1978

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Bypass Header
Drain Line Steam Leak

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2(d) since it represents abnormal degradation of a main steam system component.

Yours very truly,

David Musolf FOR

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/deh

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

7902080 183

-over-

A002
S 1/1
S