UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

Docket Nos. 30-00767
30-08144
30-10005
70-00737

DEC 05 1978

Clark University
ATTN: Mortimer Appley,
Ph.D., President
950 Main Street
Worcester, Massachusetts 01610

Gentlemen:

Subject: Inspection 78-01

This refers to the inspection conducted by Dr. L. Friedman of this office on November 16, 1978 of activities authorized by NRC License Nos. 20-02245-03, 04, 05, and SNM-679 and to the discussions of our findings held by Dr. Friedman with yourself and other members of your staff at the conclusion of the inspection, and to a subsequent telephone discussion between Mr. R. Anderson of your staff and Dr. Friedman on November 20, 1978.

The inspection was an examination of activities conducted under your licenses as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your licenses. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, measurements made by the inspector, and observations by the inspector.

Our inspector also verified the steps you have taken to correct the items of noncompliance brought to your attention in the enclosure to our letter dated April 7, 1977. We have no further questions regarding your action at this time.

Based on the results of this inspection, it appears that certain of your activities were not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A. These items of noncompliance have been categorized into the levels as described in our correspondence to you dated December 31, 1974. This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations.

7903050569

DEC 05 1979

Section 2.201 requires you to submit to this office, within twenty (20) days of your receipt of this notice, a written statement or explanation in reply including: (1) corrective steps which have been taken by you and the results achieved; (2) corrective steps which will be taken to avoid further items of noncompliance; and (3) the date when full compliance will be achieved.

From the discussion of our findings at the conclusion of the inspection, we understand that you intend to send a request that License No. 20-02245-05 be terminated to the U.S.N.R.C's Radioisotope Licensing Branch, Division of Fuel Cycle and Materials Safety, Washington, D.C. 20555. In this request, please enclose the attached form 314 filled out to show that all licensed materials have been transferred to Clark University, NRC License No. 20-02245-04. If your intent differs from this understanding, please notify us to that effect in your reply to this letter.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and your reply will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Robert O. McClintock

Robert O. McClintock, Chief
Materials Radiological Protection
Section

Enclosures:
1. Appendix A, Notice of Violation
2. Form 314