APR 1 0 1979

APPENDIX A

NOTICE OF VIOLATION

Florida Power Corporation
Crystal River 3

License No. DPR-72

Based on the NRC inspection March 13-16, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required, in part, by Appendix B Technical Specifications 3.1.4.a and 3.1.4.b, oxygen saturation will be measured at dusk and dawn of consecutive days, twice monthly in the outer bay, intake canal and discharge canal at the point of discharge.

Contrary to the above, the licensee failed to measure oxygen saturation at the assigned frequency during January and February, April and June 1978, in the case of the outer bay, and January and June, 1978, in the case of the canals.

This is a deficiency.

2313 130

7906260517

7906260