LICENSEE EVENT REPORT

CONTROL BLOCK: (1–6) **(PLEASE PRINT ALL REQUIRED INFORMATION)**

	LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
01	PA 7 MI 1	0 0 - 0 0 0 0 0 - 0 0	4 1 1 1 1	0 3
	(7–8 / 9–14)	(15–25)	(26–30)	(31–32)

	CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
01 CON'T		L	L	0 5 0 - 0 2 8 9	1 2 0 8 7 4	0 1 0 7 7 7
	(57–58)	(59)	(60)	(61–68)	(69–74)	(75–80)

EVENT DESCRIPTION

02 A radiation monitor RM-A2 was removed from service for During normal operation
03 corrective maintenance which constitutes operation in a degraded
04 mode permitted by a limiting condition for operation. Monitor
05 RM-A2 was dried out and heat tape was applied to the piping
06 to prevent further occurrences. 76-45/3L

	SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07	A B	B	X X X X X X	Z	Z 9 9 9	Y
	(9–10)	(11)	(12–17)	(43)	(44–47)	(48)

CAUSE DESCRIPTION

08 Design of the system is the cause of the occurrence
09 in that the temperature difference between the monitor
10 and the air monitored causes condensation in the monitor

	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11	E	1 0 0	NA	B	NA
	(9)	(10–12)	(13–44)	(45)	(46–80)

	FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12	Z	Z	NA	NA
	(9)	(10)	(11–44)	(45–80)

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION
13	0 0 0	Z	NA
	(7–8 / 9–11)	(12)	(13–80)

PERSONNEL INJURIES

	NUMBER	DESCRIPTION
14	0 0 0	NA
	(7–8 / 9–11)	(12–80)

OFFSITE CONSEQUENCES

15 NA (7–8 / 9–80)

LOSS OR DAMAGE TO FACILITY

	TYPE	DESCRIPTION
16	Z	NA
	(7–8 / 9)	(10–80)

PUBLICITY

17 NA (7–8 / 9–80)

ADDITIONAL FACTORS

18 NA (7–8 / 9–80)

19 (7–8 / 9–80)

NAME: [illegible] PHONE: 923-1621 ext E-114

POOR ORIGINAL

1481 089

7910250 594

GPO 881-667