Consumers Power Company

Stephen H. Howell
Senior Vice President

General Offices: 1945 West Parnall Road, Jackson, Michigan 49201 • (517) 788-0453

December 14, 1979
Howe-311-79

Mr J G Keppler, Regional Director
Office of Inspection and Enforcement
US Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

MIDLAND NUCLEAR PLANT
UNIT NO 1, DOCKET NO 50-329
UNIT NO 2, DOCKET NO 50-330
UNIT NO 1, REACTOR VESSEL BROKEN ANCHOR BOLT

Reference: Letter SHHowell to JGKeppler; Midland Nuclear Plant; Unit No 1, Docket No 50-329; Unit No 2, Docket No 50-330; Unit No 1 Reactor Vessel Broken Anchor Bolt; Howe-267-79; dated October 12, 1979.

This letter, as was the referenced letter, is an interim 50.55(e) report concerning the broken anchor bolt in the Unit 1 reactor vessel support skirt flange. The attachment to this letter provides a status of the actions being taken to resolve this condition.

Another report, either interim or final, will be sent on or before March 3, 1980.

WRB/lr

Attachment: Broken Reactor Vessel Anchor Bolt in Unit 1 Status Report, dated December 5, 1979

CC: Director of Office of Inspection & Enforcement
Att: Mr Victor Stello, USNRC (15)

Director, Office of Management
Information and Program Control, USNRC (1)

1528 100

3019
1 S 1/1

7912110365

S