TIC
50-344

CREATORS OF ELECTRICAL
POWER SUPPLY SYSTEMS

POWER SYSTEMS
A MORRISON-KNUDSEN DIVISION

101 GELO ROAD / POST OFFICE BOX 1928
ROCKY MOUNT, NORTH CAROLINA 27801
PHONE: (919) 977-2720 / TWX: (510) 929-0725

January 23, 1980

80 JAN 25 All : 25
USNRC REGION II
ATLANTA, GEORGIA

Nuclear Regulatory Commission
Region II Office
101 Marietta St. N.W.
Suite 3100
Atlanta, Georgia 30333

Reference: NRC IE Information Notice No. 79-23
Emergency Diesel Generator Lube Oil Cooler

Dear Sir:

We have been informed that there has been an Electro Motive Division of General Motors lube oil cooler failure at the Portland General Electric Trojan #1 Plant in Rainier, Oregon.

The nature of the failure is similar to that reported in the NRC IE Information Notice No. 79-23. We have requested a section of the failed core be returned to General Motors for analysis.

Very truly yours,

POWER SYSTEMS
A MORRISON-KNUDSEN DIVISION

Harry W. Falter
Division Engineer

HWF:sjw

1946 128

OFFICIAL COPY

8002110370