NAVAL POSTGRADUATE SCHOOL
MONTEREY, CA. 93940

RECEIVED
JAN 4 1979
REGION V
INSPECTION & ENFORCEMENT

NC4(005)/s1
28 December, 1978

From: Professor F. R. Buskirk, Chairman, Radiological Safety and Isotopes Committee
To: H. E. Book, Chief Fuel Facility and Materials Safety Branch
U. S. Nuclear Regulatory Commission Region V
Suite 202, Walnut Creek Plaza
1990 N. California Boulevard
Walnut Creek, CA. 94596

Info: NNPU, Port Hueneme

Subj: Corrections of Violations Found During NRC Inspection of Naval Postgraduate School activities authorized by Nuclear Regulatory Commission License's SNM-965 and 04-02579-04, 5-7 December 1978

Ref: (a) NRC letters to NPS dated 15 Dec 78, same subject

1. License No. SNM-965

a. Violation noted on Appendix A of reference (a) has been corrected by moving the material from the north wall of Room 206 of Building 234 to the west wall of the same room. No hallway exists on the west wall of the building. Measurements of dose rate of the material have been taken on the opposite side of the wall from the storage site and the readings have been "0". The readings were taken by an instrument calibrated on 13 Dec 1978.

2. License No. 04-02579

a. Violation noted on Appendix A of reference (a) has been corrected. The instruments referred to in reference (a) were transported to NAVELEX Mare Island on 13 December 1978. All instruments in the Physics and Chemistry Department have been calibrated. Instruments will be calibrated every six months as stated in the license application dated March 26, 1976.

W. H. Bodeback, Radiation Protection Officer
for F. R. Buskirk

F. R. Buskirk
Chairman,
Radiological Safety and Isotopes
Committee

7902020010