UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

30 OCT 1978

Docket No. 99900025/78-02

Southwest Fabricating & Welding Co., Inc.
Attn: Mr. N. H. Moerke
Vice President, Engineering
7525 Sherman Street, PO Box 9449
Houston, Texas 77011

Gentlemen:

Thank you for your letter of October 12, 1978, in response to our letter dated September 8, 1978. As a result of our review, we find that additional information, as discussed with you during a telephone call on October 27, 1978, is needed on the following:

Items A and B

Previous commitments i.e., indoctrination and training of personnel, made for steps to prevent recurrence on similar past findings, have not eliminated errors in MRS utilization relative to your QA Program Commitments. Please describe what additional actions are planned to assure the effectivity of your current proposed indoctrination and training of personnel.

Please provide this additional information within twenty (20) days in order that we may complete our review in a timely manner.

Sincerely,

Uldis Potapovs

Uldis Potapovs, Chief
Verdor Inspection Branch

7902020063