LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | G A E I H 1 | (2) 0 0 0 0 0 0 0 0 0 0 0 0 | (3) 4 1 1 1 1 | (4) | (5)
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 2 1 (7) | 0 2 2 7 7 9 (8) | 0 3 1 4 7 9 (9)
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 | During steady state operation while attempting to perform HNP-1-3303, HPCI Pump
3 | Rated Flow, the procedure had to be discontinued due to variations in the speed
4 | of the HPCI turbine. HPCI was declared inoperable per Technical Specifications
5 | 3.5.D.2. The ADS, RCIC, RHR system, LPCI mode, and core spray systems were
6 | immediately demonstrated to be operable. There were no effects upon the public
7 | health or safety.
8 |
8 9 80

9 | SYSTEM CODE S F (11) | CAUSE CODE E (12) | CAUSE SUBCODE E (13) | COMPONENT CODE I N S T R U (14) | COMP. SUBCODE E (15) | VALVE SUBCODE Z (16)
8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 | — | SEQUENTIAL REPORT NO. 0 1 7 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN D (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER W 2 9 0 (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause was attributed to turbine control loop failure. The controls were calibrated
11 | and the actuator was determined to be operable. After the actuator was replaced the
12 | HPCI Rated Flow procedure and HPCI Quick Start test were successfully completed.
13 |
14 |
8 9 80

FACILITY STATUS E (28) | % POWER 0 9 8 (29) | OTHER STATUS NA (30) | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance Testing
15 | 8 9 10 12 13 44 45 46 80

ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
16 | 8 9 10 11 44 45 80

PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA
17 | 8 9 11 12 13 80

PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA
18 | 8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION NA
19 | 8 9 10 80

PUBLICITY ISSUED N (43) | DESCRIPTION (45) NA
20 | 8 9 10 68 69 80

7903270352

NRC USE ONLY

NAME OF PREPARER R. T. Nix — PHONE (912) 367-6686
Superintendent of Maintenance

GPO 917-424