APPENDIX A

NOTICE OF VIOLATION

License No. 07-01173-03 Docket No. 30-14700

Based on the results of an NRC inspection conducted on April 1, 1980, it appears that certain of your activities were not conducted in full compliance with NRC regulations and the conditions of your license as indicated below:

1. 10 CFR 34.3(a) requires that an individual not be permitted to act as a radiographer until he has received copies of and been instructed in the applicable sections of Parts 19 and 20.

   Contrary to this requirement, as of April 1, 1980, you had not provided copies of Parts 19 and 20 or appropriate instructions to one radiographer in your employ.

   This is an infraction.

2. 10 CFR 71.5 requires that prior to the delivery of any licensed material to a carrier for transport you comply with the applicable regulations of the Department of Transportation as contained in 49 CFR 170-189.

   Contrary to this requirement, you delivered an Iridium-192 source to a carrier for transport in December 1979 and failed to include the radionuclide, activity in curies, category of label applied, and the transport index on the shipping paper as required by 49 CFR 172.203.

   This is an infraction.

3. 10 CFR 20.408 requires that you make a report to the Nuclear Regulatory Commission of the radiation exposure of each individual who has terminated employment.

   Contrary to this requirement, as of April 1, 1980, you failed to provide the required report to the Commission for three individuals who terminated their employment prior to February 1980.

   This item is a deficiency.

4. 10 CFR 20.409(b) requires that you make a report to the individual involved of the radiation exposure upon termination of employment.

   Contrary to this requirement, as of April 1, 1980, you failed to provide the required report to an individual who terminated employment in December 1979.

   This item is a deficiency.

8007310 701