MATERIAL TRANSMITTED HEREWITH
CONTAINS 2.790 INFORMATION

NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30303

Report No.: 70-824/78-13

Docket No.: 70-824

License No.: SNM-778

Safeguards Group: 1

Licensee: Babcock and Wilcox
Lynchburg Research Center
P. O. Box 1260
Lynchburg, Virginia 24505

Inspection conducted: November 16-17, 1978

Inspectors: J. W. Bates
J. S. C. Robertson

Reviewed by: William B. Terna, for 12-6-78
G. H. Williams, Chief Date
Material Control and Accountability Section
Safeguards Branch

Inspection Summary

Inspection on November 16-17, 1978 (Report No. 70-824/78-13)
Areas Inspected: Routine, unannounced inspection of facility organization, facility operation, measurements and management of material control system. The inspection involved nineteen inspector-hours on site by two NRC inspectors.
Results: Of the four areas inspected, no apparent items of noncompliance or deviations were identified in three areas; one apparent item of noncompliance was identified in the other area (deficiency: failure to make measurements of standards twice weekly for volumes discharged through the liquid waste system (78-13-01)).

S-F2 78 - 155
Copy ____ of ____ Copies
3 Pages

This Document is not to be reproduced without specific approval of IE:II

7901290 325

MATERIAL TRANSMITTED HEREWITH
CONTAINS 2.790 INFORMATION